



FJERNVARME HORSENS

Information concerning safety
at the woodchip receptor

BRÜNING
GROUP

Welcome to Horsens Fjernvarme

Horsens Fjernvarme receives large amounts of woodchips for the production of district heating each and every day, and a large number of these woodchips are imported. This leaflet contains important information about things you need to keep in mind when offloading woodchips.

Opening hours Monday to Friday from 7am to 5pm

Emergency number: +45 61 14 01 55

1. Personal protective equipment



2. Arrival

When you arrive at the premises of Horsens Fjernvarme, drive up onto the weighbridge and take the "Brüning Weigh Card" from the yellow cabinet beside the weighbridge in order to begin the delivery process.

Weighbridge

Woodchip Sample

Bunker

Storage Area





Remember that for space and safety reasons, you may only enter the facility when offloading and at no other time.

3. Weighing in your truck

Once you have collected the “Brüning Weigh Card” from the yellow cabinet beside the weighbridge, you should then drive up to the barrier. Stop your truck. Insert the weigh card and wait for a weigh-in receipt. Take the weigh card and the weigh-in receipt and drive onwards to the woodchip bunker.



4. Offloading into the bunker – instructions

Turn your truck around and back up to a free gate with a green light. Be aware that you should only use a bunker if there is enough space. If there is not enough space in the bunker, then you can offload at the storage area (see page 1).

Prepare the truck for offloading. The barrier will open automatically.



Remember! You must wear personal protective equipment whenever you leave your vehicle. Refer to point 1. Violation of this requirement will result in your expulsion from the site.

5. Offloading and sample-taking

Remember to take a sample when offloading using the handle with attached bucket. Then put the sample into the white bucket which you will find at the side of the gate. Drive back a few meters once you have finished offloading. Wait as the barrier closes. You may now clean up any spillage yourself and close the doors to your truck.



6. Delivering the woodchip sample

Put the weigh slip into the bucket with the woodchip sample and deliver it to the sample room.



7. Weighing out and returning the weigh card

Drive up onto the weighbridge to the far right by the exit, insert the weigh card and weight for a weigh-out receipt. The receipt will be printed automatically by the dispenser. Return the weigh card to the same yellow cabinet that you collected it from upon arrival. You will also find a stamp in the yellow cabinet which you can use to stamp your transport documents. **Have a safe onward journey!**



Safety rules

If you cause any damage to the barrier or any other equipment, you must inform staff at the weighing booth of this immediately. You will be invoiced for the cost of repair.

The procedure for offloading woodchips must be followed at all times.

Violation of the safety rules may result in your immediate expulsion from the site.

The Danish Working Environment Authority's AT Guideline D.2.2 must be followed, which means that: The employers of the incineration facility and the driver shall collaborate to ensure the security of everyone who is present at the facility. This duty of collaboration means that the drivers must follow the same rules that apply to the incineration facility's own staff.

Instructions given by facility staff must be followed.

Video Surveillance:

The facility is monitored by CCTV.

Alcohol and narcotic substances:

You must not consume or be under the influence of alcohol or narcotic substances when at the facility.

Smoking Policy:

Smoking is not permitted.

BRÜNING
GROUP

Auf der Muggenburg 44, 28217 Bremen, Germany

Tel. +49 421 - 64361 0
mail@bruening-group.dk

www.bruening-group.com